

Approved For Release 2008/01/29 : CIA-RDP83-00418R007600620001-8

This is UNEVALUATED Information

INFORMATION REPORT INFORMATION REPORT

CENTRAL INTELLIGENCE AGENCY

This material contains information affecting the National Defense of the United States within the meaning of the Espionage Laws, Title 18, U.S.C. Secs. 793 and 794, the transmission or revelation of which in any manner to an unauthorized person is prohibited by law.

SUBJECT 1. Soviet Naval Activities in Black Sea Ports 2. Soviet Naval and Air Activities at NO. PAGES 2. Soviet Naval and Air Activities at NO. PAGES 2. Soviet Naval and Air Activities at NO. PAGES 2. REQUIREMENT NO. PREFERENCES DATE OF NNO. PRACE & SOURCE EVALUATIONS ARE DEFINITIVE. APPRAISAL OF CONTENT IS TENTATIVE. 1. reports, attachments a through k, regarding Soviet naval and air activities in the Black Sea area a. Two-page report, with an appending sketch, about port controls, facilities, installations, air activities, and activities of the bort and naval activities at the port of Batumi b. Two-page report, with an appending sketch, about port facilities, installations, Soviet merchant and naval vessels at the port of Novorossiysk c. One-page report concerning diving tenders, minelayers, minesweepers, and a concrete-hulled vessel at the port of Novorossiysk d. Two-page report about navigational aids, port facilities, Soviet naval vessels, and observations of port improvements at the port of Novorossiysk an encounter with a Soviet destroyer near Sevastopol e. One-page report about port facilities, Soviet, Egyptian, and Israeli tankers loading oil, Soviet naval vessels, port personnel, and activities of coastal searchlights at the port of Tuapse f. One-page report about Soviet naval and merchant vessels, port facilities, and port communications center at the port of Poti	<u>-R-E-T</u> 25X1	S-E-C-R-E-	
DBJECT 1. Soviet Naval Activities in Black Sea Ports 2. Soviet Naval and Air Activities at NO. PAGES 2. Soviet Naval and Air Activities at NO. PAGES 2. Soviet Naval and Air Activities at NO. PAGES 3. REGUIREMENT NO. REFERENCES ATE OF HRO. ALCE & ATE ACO. SOURCE EVALUATIONS ARE DEFINITIVE. APPRAISAL OF CONTENT IS TENTATIVE. 1. reports, attachments a through k, regarding Soviet naval and air activities in the Black Sea area a. Two-page report, with an appending sketch, about port controls, facilities, installations, air activities, and activities of the bort and naval activities at the port of Batumi b. Two-page report, with an appending sketch, about port facilities, installations, Soviet merchant and naval vessels at the port of Novorossiysk c. One-page report concerning diving tenders, minelayers, minesweepers, and a concrete-hulled vessel at the port of Novorossiysk d. Two-page report about navigational aids, port facilities, Soviet naval vessels, and observations of port improvements at the port of Novorossiysk an encounter with a Soviet destroyer near Sevastopol e. One-page report about port facilities, Soviet, Egyptian, and Israeli tankers loading oil, Soviet naval vessels, port personnel, and activities of coastal searchlights at the port of Tuapse f. One-page report about Soviet naval and merchant vessels, port facilities,	DEDORT	IISSR (Plack Soc.)	MINITOV
Sea Ports 2. Soviet Naval and Air Activities at NO. PAGES 2. the Ports of Batumi and Poti REFERENCES REFERENCES ACE & ATE ACQ. SOURCE EVALUATIONS ARE DEFINITIVE. APPRAISAL OF CONTENT IS TENTATIVE. 1. reports, attachments a through k, regarding Soviet naval and air activities in the Black Sea area a. Two-page report, with an appending sketch, about port controls, facilities, installations, air activities, and activities of the port and naval activities at the port of Batumi b. Two-page report, with an appending sketch, about port facilities, installations, Soviet merchant and naval vessels at the port of Novorossiysk c. One-page report concerning diving tenders, minelayers, minesweepers, and a concrete-hulled vessel at the port of Novorossiysk d. Two-page report about navigational aids, port facilities, Soviet naval vessels, and observations of port improvements at the port of Novorossiysk an encounter with a Soviet destroyer near Sevastopol e. One-page report about port facilities, Soviet, Egyptian, and Israeli tankers loading oil, Soviet naval vessels, port personnel, and activities of coastal searchlights at the port of Tuapse f. One-page report about Soviet naval and merchant vessels, port facilities,	25X		
The Ports of Batumi and Poti REFERENCES REFERENCES SOURCE EVALUATIONS ARE DEFINITIVE. APPRAISAL OF CONTENT IS TENTATIVE. 1. reports, attachments a through k, regarding Soviet naval and air activities in the Black Sea area a. Two-page report, with an appending sketch, about port controls, facilities, installations, air activities, and activities of the port and naval activities at the port of Batumi b. Two-page report, with an appending sketch, about port facilities, installations, Soviet merchant and naval vessels at the port of Novorossiysk c. One-page report concerning diving tenders, minelayers, minesweepers, and a concrete-hulled vessel at the port of Novorossiysk d. Two-page report about navigational aids, port facilities, Soviet naval vessels, and observations of port improvements at the port of Novorossiysk an encounter with a Soviet destroyer near Sevastopol e. One-page report about port facilities, Soviet, Egyptian, and Israeli tankers loading oil, Soviet naval vessels, port personnel, and activities of coastal searchlights at the port of Tuapse f. One-page report about Soviet naval and merchant vessels, port facilities,	25X1	Sea Ports	
SOURCE EVALUATIONS ARE DEFINITIVE. APPRAISAL OF CONTENT IS TENTATIVE. 1.	REQUIREMENT		
1. reports, attachments a through k, regarding Soviet naval and air activities in the Black Sea area a. Two-page report, with an appending sketch, about port controls, facilities, installations, air activities, and activities of the port and naval activities at the port of Batumi b. Two-page report, with an appending sketch, about port facilities, installations, Soviet merchant and naval vessels at the port of Novorossiysk c. One-page report concerning diving tenders, minelayers, minesweepers, and a concrete-hulled vessel at the port of Novorossiysk d. Two-page report about navigational aids, port facilities, Soviet naval vessels, and observations of port improvements at the port of Novorossiysk an encounter with a Soviet destroyer near Sevastopol e. One-page report about port facilities, Soviet, Egyptian, and Israeli tankers loading oil, Soviet naval vessels, port personnel, and activities of coastal searchlights at the port of Tuapse f. One-page report about Soviet naval and merchant vessels, port facilities,	REFERENCES	, r	O. ACF &
a. Two-page report, with an appending sketch, about port controls, facilities, installations, air activities, and activities of the port and naval activities at the port of Batumi b. Two-page report, with an appending sketch, about port facilities, installations, Soviet merchant and naval vessels at the port of Novorossiysk c. One-page report concerning diving tenders, minelayers, and a concrete-hulled vessel at the port of Novorossiysk d. Two-page report about navigational aids, port facilities, Soviet naval vessels, and observations of port improvements at the port of Novorossiysk an encounter with a Soviet destroyer near Sevastopol e. One-page report about port facilities, Soviet, Egyptian, and Israeli tankers loading oil, Soviet naval vessels, port personnel, and activities of coastal searchlights at the port of Tuapse f. One-page report about Soviet naval and merchant vessels, port facilities,	APPRAISAL OF CONTENT IS TENTATIVE.	SOURCE EVALUATIONS ARE DEFINITIVE. APPRA	IE ACG.
installations, air activities, and activities of the port and naval activities at the port of Batumi b. Two-page report, with an appending sketch, about port facilities, installations, Soviet merchant and naval vessels at the port of Novorossiysk c. One-page report concerning diving tenders, minelayers, and a concrete-hulled vessel at the port of Novorossiysk d. Two-page report about navigational aids, port facilities, Soviet naval vessels, and observations of port improvements at the port of Novorossiysk an encounter with a Soviet destroyer near Sevastopol e. One-page report about port facilities, Soviet, Egyptian, and Israeli tankers loading oil, Soviet naval vessels, port personnel, and activities of coastal searchlights at the port of Tuapse f. One-page report about Soviet naval and merchant vessels, port facilities,	Sea area 25X	al and air activities in the Black Sea	ne
c. One-page report concerning diving tenders, minelayers, minesweepers, and a concrete-hulled vessel at the port of Novorossiysk d. Two-page report about navigational aids, port facilities, Soviet naval vessels, and observations of port improvements at the port of Novorossiysk an encounter with a Soviet destroyer near Sevastopol e. One-page report about port facilities, Soviet, Egyptian, and Israeli tankers loading oil, Soviet naval vessels, port personnel, and activities of coastal searchlights at the port of Tuapse f. One-page report about Soviet naval and merchant vessels, port facilities,		installations, air activities, and act	. a.
and a concrete-hulled vessel at the port of Novorossiysk d. Two-page report about navigational aids, port facilities, Soviet naval vessels, and observations of port improvements at the port of Novorossiysk an encounter with a Soviet destroyer near Sevastopol e. One-page report about port facilities, Soviet, Egyptian, and Israeli tankers loading oil, Soviet naval vessels, port personnel, and activities of coastal searchlights at the port of Tuapse f. One-page report about Soviet naval and merchant vessels, port facilities,			ъ.
vessels, and observations of port improvements at the port of Novorossiysk an encounter with a Soviet destroyer near Sevastopol e. One-page report about port facilities, Soviet, Egyptian, and Israeli tankers loading oil, Soviet naval vessels, port personnel, and activities of coastal searchlights at the port of Tuapse f. One-page report about Soviet naval and merchant vessels, port facilities,	tenders, minelayers, minesweepers, he port of Novorossiysk 25X	One-page report concerning diving tend and a concrete-hulled vessel at the po	c.
e. One-page report about port facilities, Soviet, Egyptian, and Israeli tankers loading oil, Soviet naval vessels, port personnel, and activities of coastal searchlights at the port of Tuapse f. One-page report about Soviet naval and merchant vessels, port facilities,	improvements at the port of Novorossiysk	vessels, and observations of port impr	d.
	ties, Soviet, Egyptian, and Israeli 25X vessels, port personnel, and activities	One-page report about port facilities, tankers loading oil, Soviet naval vess	е.
	l and merchant vessels, port facilities, 25X		f.
g. Two-page report, with four pages of sketches appended, with gives information about Soviet destroyers engaged in surface gunnery exercises, Soviet mine laying and sweeping exercises, small high-speed craft, seacoast artillery practice, air activity, floating dry dox, Soviet naval vessels, harbor dredging, and controls at the port of Poti	n surface gunnery exercises, Soviet s, small high-speed craft, seacoast floating dry (lock, Soviet naval vessels,	about Soviet destroyers engaged in sur mine laying and sweeping exercises, sm artillery practice, air activity, floa	g.
S-E-C-K-E-T	S-E-C-K-E-T	5-E	
ATE X ARMY X NAVY X AIR X FBI AEC		ARMY X NAVY X AIR X FBI	ATE X

Approved For Release 2008/01/29 : CIA-RDP83-00418R007600620001-8	
	25
-2-	25X
t shout Coviet mayal vessels and repair facilities at	207
the nort of Novorossiysk	25
	25
i. One-page report about import and export items, port improvements,	
ship repair activities, and navigational aid; at the port of	
Novorossiysk	25
	25
j. Two-page report about mine-sweeping exercises, port facilities,	
j. Two-page report about mine-sweeping exercises, port identification, and Soviet merchant vessels at the port of Novorossiysk	25
	25
k. One-page report about Soviet naval vessels in the vicinity of	
k. One-page report about Soviet havai vessels in the vicinity of Kerch-Yenikale Strait	25
	25
	25

S-E-C-R-E-

Approved For Release 2008/01/29: CIA-RDP83-00418R007600620001-8

2. Seriet Herel Vegeole: Two Seriet craisers and two destroyers errived at Revertibility on 17 August. The craisers meeted along the harbor side of Best Breakmeter. They were of the same type. They had single stacks, two meete and were amend with two terrets with dual nounts forward and a single terret with dual nounts aft. Four or five smaller guns were nounted along the rail.

these excisers were engaged in surface firing emercises approximately he miles southwest of Heresessiak. A destroyer was tening the target. One of the craisers fired a single round which splanted beyond the target.

A mist began to fall and firing was terminated.

3. Resear Facilities: A fleeting drydeck was meeted near East Breakwater.

attachment H

SECRET

25X1

25**X**1 25**X**1

25X1

25X1

25X1 25X1

Approved For Release 2008/01/29 : CIA-RDP83-00418R007600620001-8

25X1 25X1 25X1

25X1

- to democrated Activity: Bespite a shortege of labor the part of Heverossiak is operating in a la bour schools. Large numbers of experts and imports are passing through this part. The principle experts are count, potrelous products, grain and various ares.
- plates removed from the bulls of sustent ships near Site #6 were being plates removed from the bulls of susten ships near Site #6 were being plates removed from the bulls of susten ships near Site #6 were being piled on the wherf at the Timber Basin. The wherf at Site #7 has been repaired and is being paved by military labor gamps.
- 4. Ship Repair Activity: A tug best was being repaired in the floating
- 5. <u>Nevigntional Aide</u>: The characteristics of the Book Point light have been chinged. It is now operating on a group of four flashes in six seconds full and by a ten second calipse.

attachment I

SECRET

25X1

25X1

Approved For Release 2008/01/29 : CIA-RDP83-00418R007600620001-8

On 18 September a Soviet minesweeper,
was sighted exiling south in Kerch-Menikale Strait. One gan was mounted
forward and two aft. The forceastle extended aft to the bridge. Sweeping
goar was visible near the sterm.

Riv minesweepers, of the same class were moored in Kamish-Burunski.

Two minesweepers, of the same class as above, were observed engaging
to minesweepers, are the same class as above, were observed engaging
to minesweepers, are the same class as above, were observed engaging

attachment K

SECRET

25X1

25X1

25X1 25X1

25X1

25X1

25X1 25X1

25X1

25**X**1

- 25X1 Approved For Release 2008/01/29: CIA-RDP83-00418R007600620001-8 SEUKEII These vessels are 50 to 60 noters long and earry reder neunted on a single pele mast. The single stack is reked aft. The forecastle extends aft to a point immediately about the bridge. A single turret with dual mounts is carried forward and a dual mount of the same caliber is carried aft. Anti-circraft armoment concists of four dual mounts with one pair port and starboard forward of the bridge and the other pair in the same arrangement Commont #2). Those vessels were driven just forward of the stack. into Neverossisk three hours later by a violent gale with heavy rain which began about 0600. 2. Port Facilities A large grain elevator is located 700-800 meters "sheed" . The grain is carried in pipes to three leading positions on the marr. According to the foremen in charge, each looding of Plat 1). spout has a especity of 100 tens per hour. A large, needly painted floating drydock, with the words "ATTENTION SLOW SPEED" in Russian and English on the side walls, was moored near the Bastern Hole. A cargo vessel was in the dock. Merchant Topols: A large Seviet tanker, moored "in the inner section of the Eastern where", was leaded in a very short time. vessel, which had been moored at anchor outside the harbor, driven ashere near the County Works in the gale which began at 0600 grounding espeed a crack in the stern seast approximately nine miles Oserate Care attachment At t

Approved For Release 2008/01/29: CIA-RDP83-00418R007600620001-8

25X1

25X1

25X1

25X1

25X1

25X1

25X1

25**X**1 25**X**1

25X1



Approved For Release 2008/01/29: CIA-RDP83-00418R007600620001-8

UNCODED

After the ship was meered to the quay, an INFIGAT official, two customs officers, and an official to handle the leading boarded. The seaman identification eards were checked against a list of personnel; they did not consider it necessary to see the personnel. Without searching the ship, they said the inspection was completed. They departed, taking with them the identification cards.

Passes permitting the ship's personnel to go ashere were brought to the ship the evening of the same day; there were no time restrictions on the liberty. An armed sentry was stationed on the quay.

2. Port Facilities, Installations and Activities: Outside the Petroleum Nole there was a stool not of sufficient length to close the harbor. One end was fastened to a busy and the other to the mole. Informant's sketch shows the location of this net.

Most of the petroleum handled was leaded aboard shine at the Petroleum Male

	s were leaded at the eastern	end of the harber at
8,600 to	20,000 ten tankers were moer	
	ree hoses were used at the se the largest enald be leaded	
	THE INTERIOR CONTRACTOR INC.	I REAL PROPERTY TAKE SELLI IN THE
ikers; irs. Three tankers,		loaded and sailed

discharged passengers and cargo, and sailed again

25X1

25X1

25X1 25X1 25X1 25X1

25X1 25X1

25**X**1

attackment A

25X1 25X1

25X1

The maritime agency, INFLOAT, had its quarters in the upper floor of a two-storied building located across the harbor from the Petroleum Hole. The INFLOAT agent was a tall, husky man about 50 years old.

A policeman and a customs officer were on guard at a gate to the south of site #11. About 30 to h0 meters south of this gate there was a building in which a great many police agents were observed.

Twelve motor fishing boats were moored from the stern to the quay at site #11 in front of the park. These boats were active every day; they sailed out of the port at 0500 hours and returned when it was beginning to grow dark. When both leaving from and returning to the port, these beats were delayed at the end of the Petroleum Hole for an examination. The catch of fish was unleaded at their moorings, at which there was a small fish market.

3. Air Activity:

	At about 1500 hours on 25 January, three jet planes flying from southeast to the northwest at a high speed and altitude. The wings of these planes were gray in color and set well aft on the fuselage.	25 X 1
h.	Marval Vessels and Astivities:	25 X 1
	was about 5 to 7 miles off the coast on a course of 070° ensents to Batumi.	
	a Soviet patrol boat anchored 2 or 3 miles off the coast	25 X 1
	at Makriales and another at a similar distance off Eakhaber. When	25X1
	ship had closed to a distance of about one mile from the first boat, both sailed toward Batumi at a speed of 15 to 20 miles per hour. Three hours later, when approaching Batumi, these beats were seen leaving the harbor. They took up a course of approximately OhO at a speed of about 20 miles per hour.	


When departing Batumi two patrol boats were again seen off Makriales and Kalmaber.

The patrol beats were described as being dark gray in color and 18 to 20 meters in length with a flush dock. There was a small mast but no stack or radar. Forward, there was a small caliber gun without a shield.

SECRET

25X1

25X1



	Approved For	Release 2008/01/29 :	CIA-RDP83-00418R007600620001-8	25) 25X1
· Pert Pa	cilities, Posts	llations and Activ	there there was a large quantity	
of tim	- · · ·	ne sti been qida	a facilities to look timber. A small	
Acress	from the pier e	t which	ship was meered there was a large	25)
Y00001	identified a	e a fish market. refrigorating syst	long by 30 meters wide, Thirteen fishing beats and four smaless were moored by the storm to the servals of four or five days, five	
or six in the	of these fishis evening.	g beats would dope	rt in the morning and return to per-	•
			T THE PLANE IS THE STATE DESIGNATION	
Pier A	and Pier /7.		y the stern to the quay between none of	these 25)
Pier A boats : Pier A the pie	i and Pier #7. must out to sea. I was being exte	nded by earth and iting erane and for		ee e
Pier A beats the pier A tank	i and Pier #7. rent out to sea, i was being extent, a small flow of salvaging of true reflected trueghters, one	ended by earth and iting erane and for a sunken vessel.	stene fill. Some 50 to 60 meters of ir diving tenders were engaged in the	25)
Pier # beats : Pier # the pi process A tank Three : and be	i and Pier #7. rent out to sea, i was being extens, a small flee of salvaging e or was refleated freighters, one painted and we:	nded by earth and iting erane and for sunken vessel. from the floating each usek, were dr	stene fill. Seme 50 to 60 meters of ar diving tenders were engaged in the	25.

SECRET

Approved For Release 2008/01/29 : CIA-RDP83-00418R007600620001-8

25X1

Approve	ed For Release 2008/01/29 : CIA-RDP83-00418R007600620001-8	
· • • · · · · · · · · · · · · · · · · ·	SEUREIL	
		25X
<u> </u>		
rening. Ther	sailed out of the port in the norming and returned in the vere about 60 to 70 neters long, and had flush docks, a	
riped mest se	t close to the bridge, and a single, slightly reked stack.	
pel nese usue	d with a shielded gun forward of 8.8 on in caliber, a three	
r four barrel	led machine gam aft of the stack, and sixteen depth charges	•
ntones fire th	side on double rails. Something the vessels had a rade of form of a sieven at the top of the most; in the center	r
f the automas	there was an electric lamp with hericontal alignment.	
	were painted dark gray.	
ha Milih waste	al supposed to be an ald twee doubnamen. No activities	
no fifth voca no observed as	ol appeared to be an old type destroyer. He activity	
no tag <u>e anema</u>	round this vessel lifted its anchors, and anchored it a litt	le
no observed a: no tage <u>aneron</u> noed,	round this vessel ached the vessel lifted its anchors, and anchored it a little this vessel might have been under repair.	le
no observed a: no tage <u>aneron</u> noed,	round this vessel lifted its anchors, and anchored it a litt	le
no observed a: no tage answer head,	round this vessel ached the vessel lifted its anchors, and anchored it a little this vessel might have been under repair.	le
no observed a: no tage anarom head,	cound this vessel ached the vessel lifted its anchors, and anchored it a little this vessel night have been under repair. elded guns forward and two aft; no radar une observed.	lo
no charge anama head, t had two ship	ached the vessel ached the vessel lifted its anchors, and anchored it a little this vessel might have been under repair, elded guns ferward and two aft; no radar use observed, a target for gunfire at sea was lying on the ior \$5 and Pier \$6. It was about 50 noters in length and	le
no observed as to tage anama head, had two ship	ached the vessel this vessel might have been under repair, elded guns forward and two aft; no radar was observed. a target for gunfire at sea was lying on the	le
no charge anama head, t had two ship	ached the vessel ached the vessel. lifted its anchors, and anchored it a little this vessel might have been under repair. elded guns forward and two aft; no radar was observed. a target for gunfire at sea was lying on the ier #5 and Pier #6. It was about 50 noters in length and ith radar reflectors.	
no observed as no tage anama head, t had two shid nay between P: no equipped w	ached the vessel ached the vessel. lifted its anchors, and anchored it a little this vessel might have been under repair. elded guns forward and two aft; no radar was observed. a target for gunfire at sea was lying on the ier #5 and Pier #6. It was about 50 noters in length and ith radar reflectors. ship departed the port of Noveressiyek	l o
no observed as no tage anama head, h had two shid nay between P: no equipped w	ached the vessel ached the vessel. lifted its anchors, and anchored it a little this vessel might have been under repair. elded guns forward and two aft; no radar was observed. a target for gunfire at sea was lying on the ier #5 and Pier #6. It was about 50 noters in length and ith radar reflectors.	
ne observed as ne tage annual head, had two shid had two shid hay between P: ne equipped with submarine was	ached the vessel ached the vessel. lifted its anchors, and anchored it a little this vessel might have been under repair. elded guns forward and two aft; no radar was observed. a target for gunfire at sea was lying on the ier #5 and Pier #6. It was about 50 noters in length and ith radar reflectors. ship departed the port of Noveressiyek	
no observed as we tage annual head, t had two shid may between Pr no equipped with submarine was	ached the vessel ached the vessel. lifted its anchors, and anchored it a little this vessel might have been under repair. elded guns forward and two aft; no radar was observed. a target for gunfire at sea was lying on the ier #5 and Pier #6. It was about 50 noters in length and ith radar reflectors. ship departed the port of Noveressiyek	
no observed as we tage annual head, t had two shid may between P: no equipped w: submarine was he port	ached the vessel ached the vessel. lifted its anchors, and anchored it a little this vessel might have been under repair. elded guns forward and two aft; no radar was observed. a target for gunfire at sea was lying on the ier #5 and Pier #6. It was about 50 noters in length and ith radar reflectors. ship departed the port of Noveressiyek	

SECRET


25**X**1

SECRET,

25**X**1

25**X**1

25X1



SECRET

25X1

Approved For Release 2008/01/29 : CIA-RDP83-00418R007600620001-8 25X1 25X1 25X1 25X1 25X1 25X1 25X1 25X1 attadiment C

Approved For Release 2008/01/29 : CIA-RDP83-00418R007600620001-8

SECRET

25X1

25X1 Approved For Release 2008/01/29: CIA-RDP83-00418R007600620001-8 25X1 25X1 2. Port Improvement: The pilot on SMID PODGETOR THES I FIGURE MANY 25X1 Several salvaged vessels, including sunken ships had been removed from the harber. a submerine, were "behind" the Passenger Pier. 3. Mavigational Aids: A busy was moured off the ends of the Passenger Pier and the Standard Oll Flor. A red light burned after dark on the shear-legs on the Pier. 25X1 h. Pert Facilities: The shear-legs on the 25X1 Pier had four, fixed legs. A floating drydock, containing a ship, meered on the northern side of the East Breekster. A fleating erame with a triped base and a capacity of appreximately 90 tens was in the port. 5. Haval Vescels in Port: Two destroyers and five coastal patrol vessels were morred stern to on the west side of Pier #2. The destroyers were 70-75 meters in length, finsh-decked and had single stacks raked aft. They had a single most "slightly reinfereed". Armsment consisted of a single meunt forward and aft. Reder was similar to the American 50 series and was mounted on the mast. All of these vessels used shore-supplied electric power. The destroyers did not leave their borths during the reporting period. Rach day one or two of the constal patrol craft departed Hoveressisk and returned between 1800 and 1900 the same day. The erow of the destroyers and patrol vessels carried on rowing practice after 1600 hours each day in boats with three pairs of ears. 25X1 ship was Heval Vessels at Seas challenged by a Soviet destroyer off Sevestopel. The destroyer, of 1400 and steering at 18-20 knots, requested by blinker signal 25X1 ship. The skips were one to one and a half miles spart 25X1 at the time. After receiving a reply, the destroyer altered source and sailed toward Sevastopol. The destroyer had one stack and one mast. It was larger than

attachment &

SECRET

25X1 25X1 Approved For Release 2008/01/29: CIA-RDP83-00418R007600620001-8

the two destroyers berthed at Neveropsisk.

five Seviet "speed bests Alverage saling a 260 course, in line actors, at a speed of fifteen to sighteen knots. They passed skip at a distance of 150-200 notes. Only their running lights were lit.

attackment D

SECRET,

25X1 25X1

25X1 25X1

25X1

I ACS

Two	Port Facilities: South of the four erunes on t erans, are employed in its on the Oil Pier.	he fouth Hill	are emilional for an	BENEFICIAL TOP OF	ach ₂₅ x
3.	Part Activity: Soviet	tankers were	continuously loading tanker, each of appr	at the Oil Pier. eximately 10,000 to	MG,
Wes	e leading at the Oil Pic			•	_
k.	Havel Vessel: A three berthed in the Shippar	nasted naval	training vessel, of	3000-h000 tens,	
5.	Port Persennel: The parties tired from overwork it and the other on vees	Llet who brows as the other	two pilots were not	into the port said on duty. One was	that
	A 50 year old Inflost	official,		revealed	
43	the had been transfers	ed from Novero	esisk three menths b	erere.	
th we	The stevetore forenen ough all port personnel re new happy to receive	had been feets them.	idden to escapt any I	see or aring they	
	Stevedore gango, compo			, sourchlights may	
th	Goastal Searchlighte: near shore areas from ter 2h00.	2200 to 2400 (pack evening. No obs	ervations were made	

SECRET

25X1 2. Neval Vespels: A 15,000-18,000 ten passenger vessel in use as a Soviet 25X1 naval training vessel was at anchor in the Outer Earbor This ship had a single most and fermal. Rader and red automa were carried on the bridge. A large number of 17-18 year olds in nevel uniforms were aboard. 25X1 25X1 vessel had moved to the Grain Quay, this ship borthed along after the south side of Middle Mele. Right Seviet destroyers and four patrol boats were meered stern to at the Haval Rass. One of those destroyers was dispatched for patrol daty each day. The patrol was carried on both day and night. Three destroyers, elightly larger than the eight mentioned above, were undergoing repairs. Three destroyers were berthed at North Quay. An ald destroyer was moored storm to at the Grain Quay. A reder terest for navel surface gumesy practice was observed at South Mole. The bull of the target shed was built of steel. Five sheets of eleth, in the 25X1 addition to the radar reflector, were nounted upon it. target was towed by a large tag to a position about three miles south of Feti. It was then returned to a meering 200 naters to seeward of the western breakwater. 3. Bookyard Facilities: A large floating dock was seen in the harbor of Poti. Morehant Vessels: Soviet merchant ships were leading a black ere at the North Note Casy and discharging wheat at the Grain Quay. The ere was brought to the wherf in reilroad cars. A British ship was borthod alongship South Quer. 5. Pert Communications Conter: Two radio antennas and a searchlight were mounted on the reof of a three-story building at the western and of Middle Hele. A Seviet

Approved For Release 2008/01/29: CIA-RDP83-00418R007600620001-8

25X1

LVCZ

25X1

25X1

SEGNES

SECRET

marine performed sentry duty at this building.

allachment F

Approved For Release 2	2008/01/29 : CIA-R <u>DP83</u> -0 <u>04</u> 18R007600620001-8	2
		25X1
		25 X 1
Apparently races rive control of	see by a tug	2
(Sketch #9). Firing was carried	The state of the s	2
	Funnels were capped and raked the high sheer in the boy. Hain armonest	:
a single mount. A dual mount as turret. Two machine gume were a was installed on the triped mass shaft the farmel. Destroyers on their masts. This distinction A unit of this class is shown in emercises were completed the tax aloth bodly term.	Photo /1.	2
were extrict	(See sketch fö).	
These vessels were 50 to 60 met reder was mounted. Stacks were the bridge at which point a ste sensisted of a single turnet wi sens caliber on a platform aft.	ers in length and had a single pole most upon which reled aft. The deckline broke immediately about p deum occurred. The armament of this class in dual mounts forward and a dual mount of the Anti-circust armament consisted of four dual terboard forward of the bridge and another pair seeds carried nine sweeping, nine laying goar	
Each day	two of these vessels put to sea, returning	2
to Poti in the evening.		
	SECRET	4
		2
attachment G	SECTE Att	2

25X1

25X1

25X1

25X1


25X1


25X1


25X1

25X1 25X1

, in the state of	CIA-RDP83-00418R007600620001-8
. Second Artillary Practice:	a tug,
oblied from Poti, with a tarent is	the small ealther
une neutral southwest of Labo Paleostem we use fired together. Firing continued inte	ero angagod in target practice. Three
sam susantana Santat land and unter h	seed atravely participated in the naval
mery practice described in paragraph 1	shove. The land based aircraft operated the water based aircraft
res the airbase east of Poti. ero based at Lake Paleostem.	
. Floating Brydock:	thip noved to a booth alonguide
he Ferthwest Guty in the Jener Besin (Site	e #3 on Skotch #1). A fleeting erywood Namena Railway in the Inner Basin.
rates and a constant fill. The	Andrews similar to these described
Define and the control of the contro	a manufactal ererrer on enema amounts.
n paragraph 1 above, were being repaired	in the drysper.
n paragraph 1 above, were being repaired	in the drysper.
n paragraph 1 above, were being repaired: . Havel Veccels in Parts aken part in the gumery emercious, boren	the six destroyers which had see store to, facing weet, along the The four mine layers/succepts referred
n paragraph 1 above, were being repaired: . Havel Vescals in Port: aken part in the gumery exercises, boren harf morth of Site A on attached sketch.	the six destroyers which had see every to, facing weet, along the The four mine layers/sweepers referred modistaly morth of the destroyers.
n paragraph 1 above, were being repaired: . Havel Vescels in Port: aken part in the gumery exercises, beren tarf morth of Site A on attached sketch. o in paragraph 2 above morred stern to, is any "speed beats" and "port menitor beats	the six destroyers which had set evers to, facing west, along the The four mine layers/sweepers referred smediately morth of the destroyers. F were seen in the naval base. (See
n paragraph 1 above, were being repaired : Aval Vescals in Pert: aken part in the gumery emercises, beren tarf morth of Site A on attached sketch. o in paragraph 2 above mored stern to, is lany "speed bests" and "port menitor bests (ketches h, 5, 7, 10 and 11). Each day the destroyers leaded supplies from the by	the six destroyers which had see evers to, facing weet, along the The four mine layers/succepts referred smediately north of the destroyers. F were seen in the naval base. (See ship was in port, one of sealwater on the vesters side of South
n paragraph 1 above, were being repaired in the summer emercies, beren harf north of Site A on attached sketch. In paragraph 2 above mored stern to, it is speed bests" and "port menitor bests (ketches k, 5, 7, 10 and 11). Each day the destroyers leaded supplies from the byterber, (Site 3 on Sketch f1). A large we the couthern side of Hiddle Hele. (Between the couthern side of Hiddle Hele. (Between the couthern side of Hiddle Hele.	the six destroyers which had see evers to, facing weet, along the The four mine layers/succepts referred smediately north of the destroyers. F were seen in the naval base. (See ship was in port, one of sealwater on the vesters side of South
n paragraph 1 above, were being repaired : Neval Vescals in Ports aken part in the gumery emerators, beren harf morth of Site A on attached sketch. e in paragraph 2 above meered steam to, is any "speed bests" and "port memiter bests factores k, 5, 7, 10 and 11). Each day he destroyers leaded supplies from the by herbor, (Site 3 on Stetch fl). A large ve a the couthern side of Hiddle Hele. (Betw his ship had one stack and two masts.	the six destroyers which had bee store to, facing weet, along the The four mine layers/sweepers referred mediately north of the destroyers. F were seen in the naval base. (See ship was in port, one of seel in cancuflage paint was borthed seen Sites #13 and 14 on Sketch #1).
n paragraph 1 above, were being repaired : Neval Vescals in Ports aken part in the gumery emerators, beren harf morth of Site A on attached sketch. e in paragraph 2 above meered stern to, is any "speed bests" and "port memiter bests ketches k, 5, 7, 10 and 11). Each day he destroyers leaded supplies from the by he destroyers leaded supplies from the by herber, (Site 3 on Sketch fl). A large we a the couthern side of Hiddle Hele. (Betw his skip had one stack and two maste. Harbor Bredging: Bredgers were workin and the paragraph between the new wharves wh	the six destroyers which had so store to, facing weet, along the The four mine layers/sweepers referred mediately north of the destroyers. F were seen in the naval base. (See ship was in port, one of seelmater on the vestern side of South seed in cancuflage paint was berthed seen Sites #13 and 14 on Sketch #1).
n paragraph 1 above, were being repaired : Neval Vescals in Ports aken part in the gumery emerators, beren harf morth of Site A on attached sketch. e in paragraph 2 above meered stern to, is any "speed bests" and "port memiter bests ketches k, 5, 7, 10 and 11). Each day he destroyers leaded supplies from the by he destroyers leaded supplies from the by herber, (Site 3 on Sketch fl). A large we a the couthern side of Hiddle Hele. (Betw his skip had one stack and two maste. Harbor Bredging: Bredgers were workin and the paragraph between the new wharves wh	the six destroyers which had see svere to, facing weet, along the The four mine layers/sweepers referred smediately north of the destroyers. F were seen in the naval base. (See ship was in port, one of sealwater on the vestern side of South seed in samouflage paint was berthed seen Sites #13 and 14 on Sketch #1). In at the entrance to Outer Harbor sigh will separate the naval base
n paragraph 1 above, were being repaired in the gamery emercies, beren tarf north of Site A on attached sketch. In paragraph 2 above moured stern to, it lany "speed bests" and "port menitor bests (ketches h, 5, 7, 10 and 11). Ruch day the destroyers leaded supplies from the bytarber, (Site 3 on Stetch fl). A large we as the couthern side of Middle Mole. (Between the same two masts.) Harbor Brodging: Brodgers were working the passage between the new wharves where from the remainder of Outer Marbor.	the six destroyers which had be store to, facing weet, along the The four mine layers/succepts referred mediately north of the destroyers. F were seen in the naval base. (See ship was in port, one of selurator on the vestern side of Seath seel in cancuflage paint was berthed seen Sites fl3 and it on Sketch fl). If at the entrance to Outer Harbor sigh will separate the naval base 25X**
n paragraph 1 above, were being repaired in the gumery emercious, beren tarf north of Site A on attached sketch. In paragraph 2 above moored steam to, is say "speed bests" and "port menitor bests sketches k, 5, 7, 10 and 11). Each day he destroyers leaded supplies from the by larber, (Site 3 on Sketch fl). A large we in the couthern side of Hiddle Hele. (Betwies ship had one stack and two maste. 3. Harbor Bredging: Bredgers were working the pagence between the new wharves when	the six destroyers which had be store to, facing weet, along the The four mine layers/succepts referred mediately north of the destroyers. F were seen in the naval base. (See ship was in port, one of selurator on the vestern side of Seath seel in cancuflage paint was berthed seen Sites fl3 and it on Sketch fl). If at the entrance to Outer Harbor sigh will separate the naval base 25X**
A paragraph 1 above, were being repaired along part in the gumery emercious, berentary north of Site A on attached sketch. In paragraph 2 above moured steam to, is any "speed bests" and "port menitor bests sketches k, 5, 7, 10 and 11). Each day he destroyers leaded supplies from the by he destroyers leaded supplies from the by he couthern side of Hiddle Hele. (Betwies ship had one stack and two maste. 1. Harbor Bredging: Bredgers were working the passage between the new wharves where from the remainder of Outer Harbor. 2. Harbor Entrapos Controls: The steel to the inner and eastern side of the seaward.	the six destroyers which had be store to, facing weet, along the The four mine layers/succepts referred modiately morth of the destroyers. F were seen in the naval base. (See ship was in port, one of scalarator on the western side of South seel in emouflage paint was berthed seen Sites #13 and it on Sketch #1). In at the entrance to Outer Harbor sich will separate the naval base Manys of the submarine not were seen on 25X' entrance to Outer Harbor. 25X' ship was sailing from Poti _{125Y}
. Havel Vescals in Part: sken part in the gumery emercises, beren harf morth of Site A on attached sketch. e in paragraph 2 above meered stern to, is any "speed bests" and "port menitor bests ketches k, 5, 7, 10 and 11). Rach day he destroyers leaded supplies from the br larber, (Site 3 on Stetch fl). A large we a the couthern side of Middle Mele. (Betw his skip had one stack and two maste. Harber Bredging: Bredgers were workin and the passage between the new wharves wh rea from the remainder of Outer Marber. Harber Entropes Controls: The steel to the inner and eastern side of the securard	the six destroyers which had be store to, facing weet, along the The four mine layers/succepts referred modiately morth of the destroyers. F were seen in the naval base. (See ship was in port, one of scalarator on the western side of South seel in emouflage paint was berthed seen Sites #13 and it on Sketch #1). In at the entrance to Outer Harbor sich will separate the naval base Manys of the submarine not were seen on 25X' entrance to Outer Harbor. 25X' ship was sailing from Poti _{125Y}
Havel Vescals in Ports aken part in the gumery emerators, beren harf north of Site A on attached sketch. e in paragraph 2 above meered sterm to, is any "speed bests" and "port memiter bests hetches k, 5, 7, 10 and 11). Each day he destroyers leaded supplies from the by herber, (Site 3 on Stetch fl). A large we as the couthern side of Hiddle Hele. (Betw his skip had one stack and two maste. Harbor Syndging: Bredgers were workin and the passage between the new wharves wh area from the remainder of Outer Harbor. Harbor Entrance Controls: The steel to the inner and eastern side of the securard O. Seviet Grainers:	the six destroyers which had be store to, facing weet, along the The four mine layers/succeptes referred mediately north of the destroyers. F were seen in the naval base. (See ship was in port, one of seel in cancuflage paint was berthed seel in cancuflage paint was berthed seen Sites #13 and 14 on Sketch #1). In at the entrance to Outer Harbor sich will separate the naval base Manys of the submarine set were seen on 25X entrance to Outer Harbor. 25X ship was sailing from Poti







attachment 6

SECRET

25X1 25X1